



LLC 40
400x430x781





LMC 40
400x430x1517









LHC 40
400x430x2253

LLC 40, LMC 40, LHC 40




1				
	LLC 40	LMC 40	LHC 40	
1		x8	x8	x8
2		x8	x8	x8
3		x8	x8	x8
4		x8	x8	x8
5		x4	x4	x4
6		x20	x32	x52
7		x8	x12	x18
8		x1	x1	x1
9		-	x2	x4
10		x4	x12	x20
11		-	x4	x8
12		x4	x8	x12







LLD 40, LMD 40, LHD 40




LLD 40
394x18x734



LMD 40
394x18x1470









LHD 40
394x18x2206




EAC




	<i>LLD 40</i>	<i>LMD 40</i>	<i>LHD 40</i>
<i>1</i> 	<i>x1</i>	<i>x1</i>	<i>x1</i>
<i>2</i> 	<i>x2</i>	<i>x2</i>	<i>x2</i>
<i>3</i> 	-	<i>x2</i>	<i>x2</i>
<i>4</i> 	<i>x1</i>	<i>x2</i>	<i>x2</i>
<i>5</i> 	<i>x1</i>	<i>x2</i>	<i>x2</i>
<i>6</i> 	<i>x1</i>	<i>x2</i>	<i>x2</i>
<i>7</i> 	<i>x1</i>	<i>x2</i>	<i>x2</i>
<i>8</i> 	<i>x4</i>	<i>x8</i>	<i>x8</i>
<i>9</i> 	<i>x4</i>	<i>x8</i>	<i>x8</i>
<i>10</i> <i>O</i>	<i>x2</i>	<i>x2</i>	<i>x2</i>






LMRG 40
394x20x1470

LMRG 40



1		x1
2		x2
3		x2
4		x1
5		x1
6		x2
7		x2
8		x6
9		x6
10		x2

